

Type	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Errors
		348/564.ccls. and plural\$3 near (screen display monitor) and video near (processor adapter controller accelerator)	USPAT; US-PGPUB; EPO; JPO	2003/01/20 13:03		0	
106	BRS 0	5956046.pn. and decode\$3	USPAT; US-PGPUB; EPO; JPO	2003/01/20 13:03		0	
107	BRS 169	345/1.1-3.1.ccls. and decode\$3	USPAT	2003/01/20 13:04		0	
108	BRS 30	345/1.1-3.1.ccls. and decode\$3 and tv	USPAT	2003/01/20 15:28		0	
109	BRS 25	5523769.uref.	USPAT	2003/01/20 14:20		0	
110	BRS 6	345/1.1-3.1.ccls. and decode\$3 and tv and vga	USPAT	2003/01/20 16:39		0	
111	BRS 149	348/\$.cccls. and decode\$3 and tv and vga	USPAT	2003/01/20 15:56		0	
112	BRS 65	348/\$.cccls. and decode\$3 and tv and vga and plural\$3 same display	USPAT	2003/01/20 15:56		0	
113	BRS 44	348/\$.cccls. and decode\$3 and tv and vga and plural\$3 same display and frame	USPAT	2003/01/20 15:57		0	

Type	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Errors
114	BRS 27	345/1.1-3.1.cc1s. and 345/501-520.cc1s.	USPAT	2003/01/20 16:39			0
115	BRS 2	345/1.1-3.1.cc1s. and 345/501-520.cc1s. and tv and decod\$3	USPAT	2003/01/20 16:40			0